| Item	Qty.	Description
1	2	38" Vertical Extrusion
2	1	38" Vertical Extrusion w/ Door Stop
3	1	38" Vertical Extrusion w/ S44
4,4A	2,2	18" Z45 Horizontal Extrusion
5,5A	1,1	34.44" Z45 Curved Horizontal Extrusion
6,6A	1,1	24.5085" Z45 Curved Horizontal Extrusion

Steps:
1) Connect horizontals [4] [5] [6] & [6A] between verticals [1] [2] & [3].
2) Place infills on top of horizontals [4] [5] & [6] then secure with horizontals [4A] [5A] & [6A]. Note: Velcro must face inside of assembled counter.
3) Connect door to vertical [3]. See Door Connection detail.
4) Connect shelf supports to Velcro on infills.
5) Place shelf on top of supports.
6) Place counter top on top of horizontals [4A] & [5A]. See Counter Top Lock detail.
7) Attach power cords for USB Port charging assembly.

✱ Counter Top Lock

1. Align hole with pin — Hole, Pin
2. Rotate pin. Spring will push pin into hole.

✱ Door Connection

Slide pin into hinge attached to vertical. Slide door hinge over pin. — Door Hinge, Pin, Hinge

Completed Assembly

Counter Top

Shelf

Shelf Support

Infill
Door
Infill
Infill
Infill

4A   6A   5A   4A

1   2   3   4   5   6

www.classicexhibits.com

SETUP INSTRUCTIONS

If you would like to tell us about your experience with your setup instructions please email us at **info@classicexhibits.com**

© 2018

**visionary** ™
■DESIGNS

General Setup Instructions

- Read entire setup instruction manual prior to unpacking parts and pieces.

- The setup instructions are created specifically for this configuration.

- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.

- Keep exhibit components away from heat and prolonged sun exposure. **Heat and UV exposure will warp and fade components.**

- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

Disassembly

- For loss prevention, tighten all setscrews and locks during disassembly


Hex Tool - Essential for Assembly


Part Identification - Numbering

Spline Connection

Base Plate & Extrusion Connection


Extrusion & Lock Connection

Engaged Lock

⚠ **WARNING**

🚫 DO NOT USE POWER TOOLS

🪜 LADDERS OR LIFTS MAY BE REQUIRED

⚠ ALL CONNECTIONS MUST BE TIGHTLY SECURED