



# Perfect 10 Hybrid Displays



10'

10'



WHEN DISASSEMBLING TIGHTEN ALL KNOBS TO PREVENT LOSS DURING SHIPPING

866.652.2100

Item	Qty.	Description
1	1	Left Leg Assembly
2	1	Right Leg Assembly
3	1	Right Upper Curved Vertical
3a	1	Left Upper Curved Vertical
4	1	83" w Horizontal w/ Hinge
5	1	83" w Horizontal w/ Hinge

**Steps:**



**NOTE:** Assembly may be easiest if assembled face down on floor then lifted upright.

- 1) Connect upper curved vertical extrusions [3a,3] to leg assemblies [1,2].
- 2) Connect lower and upper horizontal extrusions between vertical assemblies by slightly tightening BLACK knobs on backside of extrusion as shown.

**NOTE:** Make sure velcro faces toward back and knobs face horizontally as shown in detail.

**\*\* Various Accessories Available \*\***




**NOTE:** When assembling horizontals they should be placed approximately one inch from TOP and BOTTOM.



Step stool may be required for assembly.




**WHEN DISASSEMBLING TIGHTEN ALL KNOBS TO PREVENT LOSS DURING SHIPPING**




WHEN DISASSEMBLING TIGHTEN ALL KNOBS TO PREVENT LOSS DURING SHIPPING


Top View




Level 1



Level 2



Level 3



Level 4

- Additional Items:**
- Setup Hardware
  - Graphic
  - (3) Lights

WHEN DISASSEMBLING TIGHTEN ALL KNOBS TO PREVENT LOSS DURING SHIPPING